

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2019

Submitted Date:

07/15/2019

Document Number:

696101147**FIELD INSPECTION FORM**Loc ID 305616 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 24320Name of Operator: DIAMOND OPERATING, INC.Address: 6666 GUNPARK DR STE #200City: BOULDER State: CO Zip: 80301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Peterson, Dave	(303) 494-4420	davep@flatironenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281705	WELL	PR	01/15/2006	OW	123-23247	DUNBAR 1	PR

General Comment:

This is a WELL & BATTERY Inspection.

Wells: 1: Producing | PR

Battery: Active Operation

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	CONTAINERS		
Comment:	propane, corrosion inhibitor		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input style="width: 100%;" type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:			
Type	PIT		
Comment:	Barbed wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	

Type: Ancillary equipment	# 5	
Comment:	1: Chemical pump, plastic tank w/drip conatainment (Placarded) Corrosion inhibitor. 1: Recycle pump 3: Propane tanks.	
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:	4/4	
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	Does NOT appear plumbed to surface	
Corrective Action:		Date:
Type: Vertical Heater Treater	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	FIBERGLASS AST		40.774499,-104.219723
Comment:	Skim at pit.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	300 BBLs	STEEL AST		40.774205,-104.220004
Comment:	1: Tank is insulated.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	281705	Type:	WELL	API Number:	123-23247	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing PR.								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Culverts				
Waddles						
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: _____ Lined: _____ Pit ID: 274858 Lat: 40.774252 Long: -104.219065

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date:

Fencing:Fencing Type: LivestockFencing Condition: AdequateComment: Barbed wire

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation: NO2+ feet Freeboard: YESComment: Produced H2O w/ fiberglass tank skim

Corrective Action

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 07/11/2019 at approximately 14:49 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: DIAMOND OPERATING, INC. Location Name: DUNBAR-69N61W /4SESW Location ID: 305616 Well Name: Dunbar #1 API: 05-123-23247 Location County: Weld County, Colorado Weather: Dry with some puddles & damp soil from prior rain.</p> <p>While there, I observed: Well(s) - 1: Producing PR Battery: Active Operation</p> <p>NO: Corrective Actions observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	07/15/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101148	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4878239