

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/15/2019

Submitted Date:

07/15/2019

Document Number:

687905157**FIELD INSPECTION FORM**Loc ID 325648 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96735Name of Operator: WILLIFORD RESOURCES, L.L.C.Address: 6506 S LEWIS AVE STE 102City: TULSA State: OK Zip: 74136**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Callahan, Linda	(918) 712-8828	lcallahan3@swbell.net	e-mail receipient
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215165	WELL	PR	06/01/2017	GW	067-06770	SPRING HOLLOW MAC 3	PR

General Comment:[Site inspection with photos at the end of this report.](#)

Location				
Lease Road:				
Type	Access			
comment:	Two-track dirt road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Sign posted at pumpjack.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Contact information and 911 posted on sign.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Weeds around pumpjack.			
Corrective Action:	Control weeds per Rule 603.f.			Date: 07/25/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Ancillary equipment	# 1			corrective date
Comment:	Wellhead has stained soil around it.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: 08/15/2019
Type: Pump Jack	# 1			
Comment:				
Corrective Action:				Date:
Type: Prime Mover	# 1			
Comment:	Engine has oil leak creating stained soil below it.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: 08/15/2019
Type: Flow Line	# 2			
Comment:	1-2" flowline from wellhead to centralized crude oil tank battery. 1-1" flowline from wellhead to pumpjack engine fuel gas.			
Corrective Action:				Date:
Venting:				
Yes/No				

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Type			
Comment:			
Corrective Action:		Date:	

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	215165	Type:	WELL	API Number:	067-06770	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing.								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Culverts	Pass			
Compaction	Pass	Compaction	Pass			
				Material Handling And Spill Prevention	Pass	Spill prevention for 55 gallon drum.

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905173	Stained soil around wellhead.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879076
687905174	Leaking engine and stained soil.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879077
687905175	Weeds around equipment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879078