

Inspection Photos

API: 05-073-06621

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 5/15/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06621 | Date: 5/15/2019

Inspection Photos



Photo 1. Facing northwest along the reclaimed access road. There are areas along the road where vegetation is not establishing. Vegetation that has established does not reflect the surrounding pasture.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06621 | Date: 5/15/2019

Inspection Photos



Photo 2. Facing west toward the location. Vegetation that has established does not reflect the surrounding pasture. There are areas that are bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06621 | Date: 5/15/2019

Inspection Photos



Photo 3. Facing west toward the location. Vegetation that has established does not reflect the surrounding pasture. There are areas that are bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06621 | Date: 5/15/2019

Inspection Photos



Photo 4. Facing east toward the location. Vegetation that has established does not reflect the surrounding pasture. There are areas that are bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06621 | Date: 5/15/2019

Inspection Photos



Photo 6. Facing north toward the location. Vegetation that has established does not reflect the surrounding pasture.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06621 | Date: 5/15/2019

Inspection Photos



Photo 7. Facing toward the surrounding undisturbed pasture which contains Bou gra, Spo cry, Oli ari, Pas smi, among other native plants.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06621 | Date: 5/15/2019