

Inspection Photos
Location Name: Clifford R Haller 32-11-1
Location ID: 318153



Pic 1

Pic 2 stained soil, no BMP

Inspection Photos
Location Name: Clifford R Haller 32-11-1
Location ID: 318153



Pic 4 stained soil



Pic 5 unused propane tank/closed

Inspection Photos
Location Name: Clifford R Haller 32-11-1
Location ID: 318153



Pic 6 stained soil under load line



Pic 7 unused hose near tank battery.

Inspection Photos
Location Name: Clifford R Haller 32-11-1
Location ID: 318153



COLORADO OIL AND GAS CONSERVATION COMMISSION
40.06812, -104.96793, 4993.9ft, 272°
07/15/2019 09:46:39

Pic 8 bucket of unknown contents behind tank, no BMP used



COLORADO OIL AND GAS CONSERVATION COMMISSION
40.06838, -104.96798, 4980.9ft, 302°
07/15/2019 09:48:31

Pic 9 stained soil and open fitting on separator house/trash in separator house



Inspection Photos
Location Name: Clifford R Haller 32-11-1
Location ID: 318153



Pic 10 stained soil in separator house, possible leak



Pic 11 stained soil in separator house/possible leak

Inspection Photos
Location Name: Clifford R Haller 32-11-1
Location ID: 318153



Pic 11 trash under seperator



Pic 12