

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/15/2019

Submitted Date:

07/15/2019

Document Number:

685101322**FIELD INSPECTION FORM**

Loc ID 318153 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240725	WELL	PR	12/07/1975	OW	123-08513	CLIFFORD R HALLER 32-11 1	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	stained soil around pumping unit motor, under load line on crude oil tank, and both separator houses, and tank on back of pumping unit.. See pic 2,4,6, 9,10,11		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	08/15/2019
Type	OTHER		
Comment:	no BMP for tank by pumping unit, appears to be leaking see pic 2		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff.	Date:	07/17/2019
Type	OTHER		
Comment:	Mechanical conditions throughout location. Drum by pumping unit appears to be leaking, oily waste appears to be leaking from pumping unit motor, load line cap appears to be leaking, piping in separator houses appear to be leaking see pic 2,4,6,9,10,11		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	08/15/2019
Type	TRASH		
Comment:	Trash throughout location. see pic 8, 9, 11		
Corrective Action:	Comply with Rule 603.f .	Date:	08/15/2019
Type	UNUSED EQUIPMENT		
Comment:	hose in front of water tank see pic 7		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	08/15/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	4' barb wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	4' barb wire		
Corrective Action:		Date:	
Type	SEPARATOR		

Comment: 4' barb wire			
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment: Gas motor			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares containment with oil tank.				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
----------	---	----------	------	---------	--------

CRUDE OIL	1	300 BBLs	STEEL AST		40.068120,-104.967930	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities				
Facility ID: 240725	Type: WELL	API Number: 123-08513	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 7/15/19 at approximately 1100 I, Inspector Justin Medina conducted an on-site inspection at Fritzler Resouces Inc.- API 123-08513 -Clifford R Haller 32-11-1 in Weld County Colorado.</p> <p>While there, I observed Producing Well</p> <p>During this inspection the following possible compliance issues were observed: stained soil around pumping unit motor, under load line on crude oil tank, and both separator houses, and tank on back of pumping unit.. See pic 2,4,6, 9,10,11</p> <p>Properly treat or dispose of oily waste in accordance with 907.e 8/15/19</p> <p>no BMP for tank by pumping unit, appears to be leaking see pic 2</p> <p>Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff. 7/17/19</p> <p>Mechanical conditions throughout location. Drum by pumping unit appears to be leaking, oily waste appears to be leaking from pumping unit motor, load line cap appears to be leaking, piping in separator houses appear to be leaking see pic 2,4,6,9,10,11</p> <p>Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 8/15/19</p> <p>hose in front of water tank see pic 7</p> <p>Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 8/15/19</p> <p>Trash throughout location. see pic 8, 9, 11</p> <p>Comply with Rule 603.f . 8/15/19</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	07/15/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685101323	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4880293