

Inspection Photos
Location Name: Tiffany 4
Location ID: 451594



Unused equipment/pumping unit disabled



2) Pumping units, Tiffany 4-3 in state of TA

Inspection Photos
Location Name: Tiffany 4
Location ID: 451594



3) Discolored area of dried up fluid release

Inspection Photos
Location Name: Tiffany 4
Location ID: 451594



4) Actively leaking PBV, no labels or placarss



5) PBV no labels or placards, stained soils

Inspection Photos
Location Name: Tiffany 4
Location ID: 451594



6) PSV, no labels or placards 7/15/19



7) PSV no labels or placards 5/24/18

Inspection Photos
Location Name: Tiffany 4
Location ID: 451594



8) AST, no labels or placards 7/15/19



9) ASR no labels or placards 5/24/18

Inspection Photos
Location Name: Tiffany 4
Location ID: 451594



10) Weeds around fired equipment

Inspection Photos
Location Name: Tiffany 4
Location ID: 451594



11) Interim revegetation of weeds, west side of location



12) Weeds on east edge of location

Inspection Photos
Location Name: Tiffany 4
Location ID: 451594



13) Noxious weeds on west edge of location



14) Weeds and noxious weeds in interim reclamation area west side of location

Inspection Photos
Location Name: Tiffany 4
Location ID: 451594



15) Weedy revegetation east side of entrance to location



16) Weedy revegetation on east side of location

Inspection Photos
Location Name: Tiffany 4
Location ID: 451594



17) Housekeeping – impacted material around wellhead



Housekeeping – lube oil accumulating on ground

Inspection Photos
Location Name: Tiffany 4
Location ID: 451594



19) Sound meter location and weedy revegetation on NW corner of location