

Inspection Photos
Location Name: Energy Minerals Unit B #1
Location ID: 318873



Photo 1 well head sign faded and not legible



Photo 2 WH

Inspection Photos
Location Name: Energy Minerals Unit B #1
Location ID: 318873



Photo 3 flow lines from Well head are closed



Photo 4 Weeds around electric panel

Inspection Photos
Location Name: Energy Minerals Unit B #1
Location ID: 318873



Photo 5 Weeds on location



Photo 6 Access road covered by weeds.

Inspection Photos
Location Name: Energy Minerals Unit B #1
Location ID: 318873



Photo 7 TNK BTRY



**Photo 8 sep/meter runs and ECD equipment not running.
Weeds around equipment.**

Inspection Photos
Location Name: Energy Minerals Unit B #1
Location ID: 318873



Photo 9 Produced water tank. Appears tank overflowed inside containment. Spill



Photo 10 Dug down approx.. 1 ft next to produced water tank ground saturated with what appears to be E&P substance.

Inspection Photos
Location Name: Energy Minerals Unit B #1
Location ID: 318873



Photo 11 Produced water tank. Appears tank overflowed inside containment. Spill



Photo 12 Stained soil around inspection hatch of Crude oil tank.

Inspection Photos

Location Name: Energy Minerals Unit B #1

Location ID: 318873



Photo 13 stained soil around load line of crude oil tank



Photo 14 Unused equipment: North crude oil tank has OUT OF SERVICE in multiple spots on tank. Front load line valve is closed.

Inspection Photos
Location Name: Energy Minerals Unit B #1
Location ID: 318873



Photo 15 Stained soil underneath recirc pump



Photo 16 Mechanical issue: recirc pump appears to be leaking.

Inspection Photos
Location Name: Energy Minerals Unit B #1
Location ID: 318873



Photo 17 stained soil inside Separator house. Mechanical Issue: Piping on separator.



Photo 18 Mechanical issue: Piping on separator