

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2019

Submitted Date:

07/10/2019

Document Number:

687905108**FIELD INSPECTION FORM**
 Loc ID 325560 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
,	970-563-4000	maralextech@gmail.com	<a href="#">All Inspections</a>
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215004	WELL	PR	08/28/2006	GW	067-06609	HEIKKINEN 1-10	PR

**General Comment:**

This is a follow inspection to the previous inspection Doc#687904763. This inspection does not allieviate prior corrective actions. Corrective actions that have been completed will be noted on this report. Photos of location are at the end of this report.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds need to be controlled around equipment.		
Corrective Action:	Comply with Rule 603.f.		Date: 06/16/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:	Wildlife bird netting on top of tank still has holes and needs to be repaired or replaced.					
Corrective Action:	Comply with Rule 324 A.a.				Date:	05/23/2019

**Paint**

Condition	<input type="text"/>	
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berm has been built up around produced water tank and is compacted and sufficient and passes re-inspection.			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>

**Venting:**

Yes/No	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

**Flaring:**

Type	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

**Inspected Facilities**Facility ID: 215004 Type: WELL API Number: 067-06609 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402103752	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874948">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874948</a>
687905109	Weeds around equipment.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874937">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874937</a>
687905110	Berm Repaired.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874938">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874938</a>
687905111	Wildlife netting repair or replace.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874939">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874939</a>