

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/10/2019

Submitted Date:

07/10/2019

Document Number:

687905112**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection
311955 _____ Stewart, Joseph _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 8 Number of Comments
5 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|---------------------------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| , | 970-563-4000 | maralextech@gmail.com | All Inspections |
| Ferrin, Jeremy | | jeremy.ferrin@state.co.us | |

General Comment:

[This is a follow up inspection from the previous inspection doc#687904769. This inspection does not allieviate corrective actions from previous inspection.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused wellhead valve that was sitting on pumpjack skid has been removed. | | |
| Corrective Action: | | Date: | |
| Type | WEEDS | | |
| Comment: | Weeds around separator need to be controlled and CA from previous inspection#687904769 has not been completed. | | |
| Corrective Action: | Comply with Rule 603.f. | Date: | 06/16/2019 |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| Type | | | corrective date |
|---------------------|--|-------|-----------------|
| Pump Jack | # 1 | | |
| Comment: | #1 pumpjack exhaust oily waste from previous inspection# 687904769 has not been completed. | | |
| Corrective Action: | Comply with Rule 907.e. and 1002.f.(2) | Date: | 06/16/2019 |
| Ancillary equipment | # 2 | | |
| Comment: | Stained gravel/soil around wellhead has not been removed from prior CA inspection#687904769 | | |
| Corrective Action: | Comply with Rule 907.e. and 1002.f.(2) | Date: | 06/16/2019 |
| Pump Jack | # 1 | | |
| Comment: | #3B gearbox on pumpjack is still leaking from previous inspection#687904769 and CA has not been completed. | | |
| Corrective Action: | Comply with Rule 1002.f.(2) | Date: | 06/16/2019 |

Venting:

| | | | |
|--------------------|----------------------|-------|--|
| Yes/No | | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|----------------------|-------|--|
| Type | | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | | Date: | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| | | | | Material Handling And Spill Prevention | Fail | |

Comment: Spill prevention for engine oil day tank is sitting on location but has not been put in use. CA from previous inspection#687904769 has not been completed.

Corrective Action: Comply with Rule 1002.f.(2)B

Date: 06/16/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------------------|---|
| 402103753 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874949 |
| 687905113 | Spill prevention not in use. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874940 |
| 687905114 | Exhaust oily waste | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874941 |
| 687905115 | Stained gravel around wellhead. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874942 |
| 687905116 | Wellhead valve removed from skid. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874943 |
| 687905117 | Weeds around equipment | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874944 |
| 687905118 | Gearbox leak. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874945 |