

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2019

Submitted Date:

07/10/2019

Document Number:

689703303**FIELD INSPECTION FORM**Loc ID 335803 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1401

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

11 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
COGCC, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277373	WELL	PR	08/23/2005	GW	045-10687	CASCADE CREEK 697-15-54	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 07/09/2019 at approximately 1340 hours, I, Inspector Mike Longworth, conducted a field inspection at Laramie Energy LLC Cascade Creek 697-15-54, at Location # 335803 in Garfield County, Colorado.

Contents and NFPA labels have conflicting information. Tanks labeled for Condensate and Produced water. Tank labels having NFPA's showing Fire Hazard ranging from 1 to 4.

Photos 7,8,9,10,11,12,13, & 14 Install sign to comply with Rule 210.d.

C.A. Date 9/9/2019

Weeds growing around heated separator. Photos 3 & 4

Comply with Rule 603.f .

C.A. Date 07/20/2019

Unmarked guy line anchors

Mark guy line anchors per Rule 1003.a. Photos 5 & 6

C.A. Date 07/25/2019

Open port on top of tank. Photos 7 & 8

On 07/09/2019 at approximately 1443 hours Eric Lane of Laramie was left a message on open port and notified of 24 hour corrective action time line. A return message was received From Eric Lane at 1600 hours 07/09/2019 stating tank was not connected to other tanks and was for antifreeze not condensate and should be leaving location as early as this week.

A review of photos show tank is connected and label Condensate.

Close open port.

C.A. Date 07/10/2019

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Contents and NFPA labels have conflicting information. Tanks labeled for Condensate and Produced water. Tank labels having NFPA's showing Fire Hazard ranging from 1 to 4. Photos 7,8,9,10,11,12,13, & 14		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	09/09/2019
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-242-1234

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds growing around heated separator. Photos 3 & 4		
Corrective Action:	Comply with Rule 603.f .	Date:	07/20/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heated Separator	# 1		corrective date
Comment:	Dehy/sep combo unit.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		

Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 4		
Comment:	4 2" risers in tank battery with lock out tags have no plugs. Photos 5 & 6		
Corrective Action:	Maintain Integrity Management program for flowlines and crude oil transfer lines per rule 1104.a-e Contact Engineering Integrity Group for review of flowline status. Include COGCC FIU Inspector Mike Longworth on communications.		Date: 07/17/2019
Type: Deadman # & Marked	# 1		
Comment:	Unmarked guy line anchor. Photos 5 & 6		
Corrective Action:	Mark guy line anchor per Rule 1003.a.		Date: 07/26/2019
Type: Dehydrator	# 1		
Comment:	Out of service. Dehy/sep combo unit.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<100 BBLs	STEEL AST		,
Comment:	Open port on top of tank. Photos 7 & 8 On 07/09/2019 at approximately 1443 hours Eric Lane of Laramie was left a message on open port and notified of 24 hour corrective action time line. A return message was received From Eric Lane at 1600 hours 07/09/2019 stating tank was not connected to other tanks and was for antifreeze not condensate and should be leaving location as early as this week. A review of photos show tank is connected and label Condensate.				
Corrective Action:	Close open port.				Date: 07/10/2019

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	277373	Type:	WELL	API Number:	045-10687	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Berms	Pass					
Compaction	Pass					
		Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402102735	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874177
689703304	Inspection 689703303 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874172