

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type OTHER

Comment: PHOTO 5: IMPACTED SOIL UNDER PUMPJACK PRIME MOVER AND GEAR BOX.

Corrective Action: Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907.

Date: 08/09/2019

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type PUMP JACK

Comment:

Corrective Action:

Date:

Equipment:

corrective date

Type: Bradenhead # 1

Comment: PLUMBED TO SURFACE

Corrective Action:

Date:

Type: Deadman # & Marked # 4

Comment:

Corrective Action:

Date:

Type: Ancillary equipment # 1

Comment: TELEMETRY EQUIPMENT

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 217875 Type: WELL API Number: 071-06654 Status: PR Insp. Status: PR

Producing Well

Comment:			
Corrective Action:			Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402101804	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4873474
695100989	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4873457