

Inspection Photos

ID: 256456

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/11/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 256456 | Date: 7/11/2019

Inspection Photos



Photo 1. Facing northeast toward the reclaimed pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 256456 | Date: 7/11/2019

Inspection Photos



Photo 2. Facing east toward the reclaimed pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 256456 | Date: 7/11/2019

Inspection Photos



Photo 3. Outlet protection has been installed on the culvert with geotextile.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 256456 | Date: 7/11/2019

Inspection Photos



Photo 4. Facing west toward the slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 256456 | Date: 7/11/2019

Inspection Photos



Photo 5. There is predominately wheat growth throughout the site. There are numerous noxious weeds Scotch thistle growing throughout the site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 256456 | Date: 7/11/2019