

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/16/2019

Submitted Date:

07/16/2019

Document Number:

689703338**FIELD INSPECTION FORM**Loc ID 335214 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211549	WELL	PR	12/21/1998	GW	045-07309	UNOCAL GM 222-33	PR
260675	WELL	PR	06/06/2002	GW	045-07900	UNOCAL GM 433-33	PR

**General Comment:**

On Tuesday 07/16/2019 at approximately 1130 hours, I, Inspector Mike Longworth, conducted a field inspection at Terra GM 433-33, at Location # 335214 in Garfield County, Colorado.

During this inspection the following possible compliance issues were observed:

WARNING High pressure Natural Gas Pipeline sign/marker in center of location is broken at post and knocked over.

Repair broken sign post.

C.A. Date 7/31/2019

Weeds are coming up on location and access road into location.

Comply with Rule 603.f.

C.A. Date 07/27/2019

Piece of damaged culvert and fencing wire and wood post/stakes at intersection of access and main road.

Comply with Rule 603.f.

C.A. Date 07/27/2019

Washing and rilling on access road down hill from location.

Install or repair required BMPs per Rule 1002.f.

C.A. Date 8/17/2019

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Washing and rilling down hill from location.		
Corrective ActionL		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	WARNING High pressure Natural Gas Pipeline sign/marker in center of location is broken at post and knocked over.		
Corrective Action:	Repair broken sign post.	Date:	07/31/2019
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	911		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Piece of damaged culvert and fencing wire and wood post/stakes at intersection of access and main road.		
Corrective Action:	Comply with Rule 603.f .	Date:	07/27/2019
Type	WEEDS		
Comment:	Weeds are coming up on location and access road into location.		
Corrective Action:	Comply with Rule 603.f .	Date:	07/27/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			

Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbls	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

**Inspected Facilities**Facility ID: 211549 Type: WELL API Number: 045-07309 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 260675 Type: WELL API Number: 045-07900 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Washing and rilling on access road down hill from location.](#)Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 08/17/2019

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689703339	Inspection 689703338 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4881104">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4881104</a>