

**FORM  
INSP**Rev  
X/15

# State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/17/2019

Submitted Date:

07/17/2019

Document Number:

685101383**FIELD INSPECTION FORM**
 Loc ID 330758 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@Anadarko.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251769	WELL	SI	01/01/2019	GW	123-19573	HSR-WEICHEL 13-14	TA
412092	WELL	SI	01/01/2019	OW	123-30385	WEICHEL 14-14	SI
412093	WELL	SI	01/01/2019	GW	123-30386	WEICHEL 23-14	SI
412094	WELL	SI	05/01/2017	GW	123-30387	WEICHEL 36-14	SI
412133	WELL	SI	01/01/2019	GW	123-30395	WEICHEL 19-14	SI
412225	WELL	PA	03/20/2018	GW	123-30404	WEICHEL 33-14	PA
412226	WELL	SI	01/01/2019	GW	123-30405	WEICHEL 35-14	SI

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Plunger Lift

# 1

Comment:

Corrective Action:

Date:

Type: Bradenhead

# 1

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**Facility ID: 251769 Type: WELL API Number: 123-19573 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: TA

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 412092 Type: WELL API Number: 123-30385 Status: SI Insp. Status: SIFacility ID: 412093 Type: WELL API Number: 123-30386 Status: SI Insp. Status: SIFacility ID: 412094 Type: WELL API Number: 123-30387 Status: SI Insp. Status: SIFacility ID: 412133 Type: WELL API Number: 123-30395 Status: SI Insp. Status: SIFacility ID: 412225 Type: WELL API Number: 123-30404 Status: PA Insp. Status: PAFacility ID: 412226 Type: WELL API Number: 123-30405 Status: SI Insp. Status: SI

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules.	medinaj	07/17/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685101384	Pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4881727">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4881727</a>