

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/08/2019

Submitted Date:

07/17/2019

Document Number:

689802891**FIELD INSPECTION FORM**Loc ID 313197 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 56565Name of Operator: MERIT ENERGY COMPANYAddress: 13727 NOEL ROAD STE 1200City: DALLAS State: TX Zip: 75240**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hindle, Holly		holly@northshoreenergyllc.com	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272924	WELL	PR	11/01/2018	GW	081-07188	FEDERAL 21-33	PR

General Comment:**COGCC Inspection Report 689802891 Summary**

On Monday 7/8/2019 at approximately 13:20, I, Inspector Emily Waldron, conducted a field inspection at North Shore Exploration and Production LLC Federal #21-33, at 05-081-07188 in Moffat County Colorado.

While there, I observed Production.

During this inspection the following possible compliance issues were observed:

Merit Energy listed as operator on battery sign. See photo 2. Install sign to comply with Rule 210.b by 8/16/2019.

Merit Energy listed as operator on wellhead sign. See photo 1. Install sign to comply with Rule 210.b by 8/16/2019.

307-783-2627 is emergency contact for former operator, Merit Energy. No emergency information for current operator on location. See photos 1 and 2. Install sign to comply with Rule 210 by 8/16/2019.

Form 10 document number 401864556, submitted 2/14/2019, Approved 7/15/2019 to transfer from Merit Energy Company to North Shore Exploration and Production LLC.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 689802891.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Merit Energy listed as operator on battery sign.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	08/16/2019
Type	WELLHEAD		
Comment:	Merit Energy listed as operator on wellhead sign.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	08/16/2019
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	307-783-2627 is emergency contact for former operator, Merit Energy. No emergency information for current operator on location.		
Corrective Action:	Install sign to comply with Rule 210.	Date:	08/16/2019

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	#		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	272924	Type:	WELL	API Number:	081-07188	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No stormwater BMPs observed. No apparent soil migration; erosion or soil movement.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689802911	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4882325