

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/11/2019

Submitted Date:

07/11/2019

Document Number:

687905128**FIELD INSPECTION FORM**

Loc ID 334004 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments3 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
,	970-563-4000	maralextech@gmail.com	All Inspections
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297197	WELL	PR	01/01/2019	GW	067-09599	ARTFGANCE 33-7-14 3B	PR
297213	WELL	PR	06/25/2009	GW	067-09605	ARTFGANCE 33-7-14 1	PR

General Comment:

This is a follow up inspection from previous inspection doc#687904752. This inspection does not allieviate corrective actions from prior inspection. Completed corrective actions will be noted in this inspection report. Photos are at the end of this inspection report.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment: Weeds around pumpjack, separator and meter houses need to be controlled.

Corrective Action: Control weeds to comply with Rule 603.f.

Date: 06/16/2019

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Prime Mover

1

Comment: 33-7-14 #1 pumpjack engine is leaking oil across skid and off to the ground.

Corrective Action: Comply with Rule 1002.f.(2)

Date: 08/11/2019

Type: Pump Jack

1

Comment: 33-7-14 #1 Pump jack gearbox is leaking gear oil from seal with localized spotting on ground.

Corrective Action: Comply with Rule 1002.f.(2)

Date: 06/16/2019

Type: Pump Jack

1

Comment: 33-7-14 #3B fuel gas leak from knockout pot on drain valve was either repaired or replaced and is not leaking anymore.

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 297197 Type: WELL API Number: 067-09599 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Facility ID: 297213 Type: WELL API Number: 067-09605 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402105792	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876088
687905129	Weeds.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876062
687905130	Pumpjack gearbox leak.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876063
687905131	Engine oil leak.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876064
687905132	Engine oil leak.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876065
687905133	Engine oil leak.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876066