

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/11/2019

Submitted Date:

07/11/2019

Document Number:

687905134

FIELD INSPECTION FORM

Loc ID 333984 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53255
 Name of Operator: MARALEX RESOURCES INC
 Address: P O BOX 338
 City: IGNACIO State: CO Zip: 81137

Findings:

- 8 Number of Comments
4 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Browning, Chuck		chuck.browning@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
,	970-563-4000	maralextech@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297995	WELL	PR	05/25/2010	GW	067-09621	ARTFGANCE 33-7-14 2A	PR
298106	WELL	PR	11/01/2018	GW	067-09623	ARTFGANCE 33-7-14 3C	PR

General Comment:

This is a follow up inspection from previous inspection doc#693800271. This inspection does not allieviate corrective actions from prior inspections performed. Any completed corrective actions will be noted in this report. Photos are at the end of this inspection report.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	2-300 bbl produced water tanks and walkways. Disconnected and not in use.		
Corrective Action:	Remove unused equipment to Comply with Rule 603.f .	Date:	08/30/2019
Type	OTHER		
Comment:	Impacted soil around wellheads has not been remediated as per CA on Inspection Doc#674600120 posted 3/20/2014 and Doc#693800271 posted 5/14/19.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e. & 1002.f.	Date:	06/28/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Flow Line	# 1		corrective date
Comment:	API # 05-067-09621 ARTFGANCE 33-7-14 #2A. possible wellhead/separator flowline. Washed out 10????diameter hole ~20????NE of wellhead. Noted changing fluid levels and intermittent bubbles. Current inspection of location, as of 7/11/19 no liquid visible in 12" diameter hole. Both well heads are currently shut-in with no production.		
Corrective Action:	Investigate and respond by FIRR source of cause. If flowline cause report 1102.i and repair 1102.j Perform pressure test per 1104.b	Date:	06/28/2019

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 297995 Type: WELL API Number: 067-09621 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Shut-in due to possible flowline leak.

Corrective Action: _____ Date: _____

Facility ID: 298106 Type: WELL API Number: 067-09623 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Shut-in due to possible flowline leak.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	

Comment: Lube oil tanks at pump jack have no secondary containment.

Corrective Action: Install spill prevention per Rule 1002.f.

Date: 06/28/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402105793	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876089
687905135	No spill prevention	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876067
687905136	Shut-in well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876068
687905137	Shut-in well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876069
687905138	Possible flowline leak.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876070
687905139	Unused equipment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876071