

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2019

Submitted Date:

07/11/2019

Document Number:

687905140**FIELD INSPECTION FORM**Loc ID 306805 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|---------------------------------|
| , | 970-563-4000 | maralextech@gmail.com | All Inspections |
| Ferrin, Jeremy | | jeremy.ferrin@state.co.us | |
| Labowskie, Steve | | steve.labowskie@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 267561 | WELL | PR | 08/05/2003 | GW | 067-08800 | MOLLIE CORYNNE 33-7-2 2A | PR |

General Comment:

This is a follow up inspection from previous inspection doc#687904798. This inspection does not allieviate corrective actions from prior inspections performed. Any completed corrective actions will be noted in this report. Photos are at the end of this inspection report.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

| | | | |
|--------------------|---|-------|------------|
| Type | WEEDS | | |
| Comment: | Weeds and dead brush around equipment are controlled. | | |
| Corrective Action: | | Date: | |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused equipment parts sitting on concrete and plastic tub out front of fence has been removed. | | |
| Corrective Action: | | Date: | |
| Type | TRASH | | |
| Comment: | Used rags and pads around equipment. | | |
| Corrective Action: | Clean up trash and dispose of properly per Rule 603.f. | Date: | 06/01/2019 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

| | | | |
|---------------------------|--|-------|-----------------|
| Type: Ancillary equipment | # 1 | | corrective date |
| Comment: | Wellhead is leaking from packing gland or oil box. | | |
| Corrective Action: | Repair/maintain wellhead per Rule 1002.f.(2) | Date: | 05/29/2019 |
| Type: Pump Jack | # 1 | | |
| Comment: | Pumpjack gearbox seals that were leaking gear oil down unit and on concrete on both the east and west side of unit appear to have been repaired and oily waste cleaned up. | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 267561 Type: WELL API Number: 067-08800 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 402105794 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876090 |
| 687905141 | Weeds controlled and unused equipment removed. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876072 |
| 687905142 | Gearbox seal repaired east side. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876073 |
| 687905143 | Leaking wellhead packing gland or oil box. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876074 |
| 687905144 | Gearbox seal repaired west side. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876075 |