

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2019

Submitted Date:

07/11/2019

Document Number:

687905145**FIELD INSPECTION FORM**
 Loc ID 333710 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
,	970-563-4000	maralextech@gmail.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265538	WELL	PR	10/15/2003	GW	067-08770	JENNIE ROSE 33-7-3 1	PR

**General Comment:**

This is a follow up inspection from previous inspection doc#687904758. This inspection does not allieviate corrective actions from prior inspections performed. Any completed corrective actions will be noted in this report. Photos are at the end of this inspection report.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds and vegetation around separator, meter house need to be controlled.		
Corrective Action:	Comply with Rule 603.f.		Date: 05/26/2019
Type	UNUSED EQUIPMENT		
Comment:	Parts laying on 55 gallon drum have been removed. Sucker rod and timbers laying along side of pumpjack currently still there.		
Corrective Action:	Comply with Rule 603.f.		Date: 06/16/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:	Engine oil with staining of gravel/soil below engine. Repair leaking equipment and remediate soil and gravel and dispose of in accordance with regulations. Soil/gravel was removed from underneath pumpjack engine, but not disposed of properly and is now spread along the northern side of pumpjack on ground.		
Corrective Action:	Comply with Rule 1002.f.(2)		Date: 07/16/2019

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

<b>Inspected Facilities</b>				
Facility ID: 265538	Type: WELL	API Number: 067-08770	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing.			
Corrective Action:				Date:

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	Spill prevention for 55 gal drum

Comment: 55 gallon drum sitting at separator, with vacuum breaker hose into barrel has spill prevention in place.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402105796	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876092">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876092</a>
687905146	Weeds.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876076">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876076</a>
687905147	Unused equipment.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876077">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876077</a>
687905148	Oily gravel/soil removed from under engine.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876078">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876078</a>
687905149	Oily gravel/soil not disposed properly.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876079">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876079</a>
687905150	Oily gravel/soil not disposed properly.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876080">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876080</a>
687905151	Spill prevention on 55 gal drum.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876081">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876081</a>