

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2019

Submitted Date:

07/11/2019

Document Number:

693500741**FIELD INSPECTION FORM**

Loc ID 318463 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	All inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241337	WELL	PR	03/07/1977	OW	123-09126	WELD COUNTY C 2	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well Head sign faded not legible.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	08/11/2019

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil in front of PU base.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	08/11/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	Square tubing		
Corrective Action:		Date:	

Equipment:

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	241337	Type:	WELL	API Number:	123-09126	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday July 11, 2019 at approximately 1:03PM, I, Inspector Randy Silver conducted an on-site inspection at a KP Kauffman site Weld County C #2, at API# 05-123-09126 in Weld County Colorado.</p> <p>While there, I observed a well site.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>WH sign: Rule 210 e Corrective action date of 8-11-19 see photo 2</p> <p>Stained soil: Rule 907 e Corrective action date of 8-11-19 See photo 3</p> <p>At time of inspection I observed well head sign what appeared to be sun faded and illegible, also what appeared to be stained soil in front of PU base.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	07/11/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402105884	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876145
693500742	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876142