

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2019

Submitted Date:

07/11/2019

Document Number:

696200374**FIELD INSPECTION FORM**
 Loc ID 454195 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10657Name of Operator: PCR OPERATING LLCAddress: 4040 BROADWAY STREET #510City: SAN ANTONIO State: TX Zip: 78209**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Young, Rob		rob.young@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
		dkunovic@passcreekresource s.com	
		dnr_cogccenforcement@state .co.us	
		gwehrer@passcreekresource s.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454195	LOCATION	AC	03/05/2018		-	ADENA SOUTH WATER PLANT 158-24-41	RI

**General Comment:**

This is a follow-up good housekeeping inspection. Any corrective action(s) from previous inspections that have not been addressed are still applicable.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
Comment:	There appears to have been a spill at the meter run equipment on the west end of the location; Stained soils evident at the meter sheds and adjacent lands.			
Corrective Action:	Contact area EPS. Properly treat or dispose of waste and stained soils on location in accordance with Rule 907.e.			Date: 08/11/2019

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Gas Meter Run	#		corrective date
Comment:			
Corrective Action:	Gas freely venting from the meter run on the west end of the location. No approved Form 4 request to vent.		Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 454195 Type: LOCATION API Number: - Status: AC Insp. Status: RI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402105539	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4875922">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4875922</a>
696200375	Venting @ meter	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4875911">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4875911</a>
696200376	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4875912">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4875912</a>