

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/18/2019

Submitted Date:

07/18/2019

Document Number:

687905232**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 306927 Stewart, Joseph 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**18 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279085	WELL	PR	07/29/2005	GW	067-09060	KAIME FEDERAL 2	PR

General Comment:[Site inspection with photos at the end of this report.](#)

Location				
Lease Road:				
Type	Access			
comment:	Gravel road access.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Sign posted at entrance to location.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Labels/placards posted on tank and sign.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Contact information posted on tank and sign.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Unused piping and insulated piping sitting along cattle panel fence.			
Corrective Action:	Remove unused equipment per Rule 603.f.			Date: 08/18/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	TANK BATTERY			
Comment:	Cattle panels around produced water tank.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Cattle panels around wellhead and pumpjack.			
Corrective Action:				Date:
Type	SEPARATOR			
Comment:	Cattle panels around separator and meter house.			
Corrective Action:				Date:
Equipment:				
Type: Gas Meter Run	# 1			corrective date
Comment:				

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Natural gas powered engine exhaust muffler is staining the soil, gravel and concrete with oily fluid.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 08/18/2019
Type: Ancillary equipment	# 1		
Comment:	Wellhead with stained soil/gravel around the base.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 08/18/2019
Type: Bradenhead	# 1		
Comment:	PVC bradenhead access.		
Corrective Action:		Date:	
Type: Flow Line	# 6		
Comment:	1-3" flowline from wellhead to separator. 1-2" flowline from separator blowdown to produced water tank. 1-2" flowline from separator dump valve to offsite produced water gathering system. 1-1" flowline from separator to pumpjack engine fuel gas. 1-3" flowline from separator to meter house. 1-4" flowline from meter house to offsite dogleg.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	On separator stack.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	279085	Type:	WELL	API Number:	067-09060	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing.								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
				Material Handling And Spill Prevention	Pass	Spill prevention for engine oil day tank.
Gradient Terraces	Pass	Gravel	Pass			
Compaction	Pass	Culverts	Pass			
Ditches	Pass	Ditches	Pass			
Berms	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402114749	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4883792
687905244	Unused piping.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4883779
687905245	Muffler staining gravel.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4883780
687905246	Exhaust staining gravel.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4883781
687905247	Exhaust oil on concrete.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4883782
687905248	Stained gravel around wellhead base.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4883783
687905249	Location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4883784