

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/09/2019

Submitted Date:

07/12/2019

Document Number:

694900033**FIELD INSPECTION FORM**
 Loc ID 334640 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|-------|---|---------|
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| , Caerus | | COGCC.inspections@caerus oilandgas.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 273514 | WELL | PR | 05/12/2005 | GW | 045-10253 | COUEY 23-1D (G23W) | PR |
| 273515 | WELL | PR | 05/06/2005 | GW | 045-10254 | COUEY 23-7 (G23W) | PR |
| 273516 | WELL | PR | 05/03/2005 | GW | 045-10255 | COUEY 23-2C (G23W) | PR |
| 273517 | WELL | PR | 05/09/2005 | GW | 045-10256 | COUEY 23-7C (G23W) | PR |

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: No emergency contact number posted for local EMS

Corrective Action: install sign to copy with 210.b

Date: 08/12/2019

Overall Good: ☒**Spills:**

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|---------------------------|-------|--|
| Type | LOCATION | | |
| Comment: | barb wire around location | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|-----------------------------------|-------------------------------|-------|-----------------|
| Type: Ancillary equipment | # 1 | | corrective date |
| Comment: | methanol tank in tank battery | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pig Station | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER | 1 | 400 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|--------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 273514 | Type: | WELL | API Number: | 045-10253 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 273515 | Type: | WELL | API Number: | 045-10254 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 273516 | Type: | WELL | API Number: | 045-10255 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 273517 | Type: | WELL | API Number: | 045-10256 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | Pass | | | | | |
| | | Compaction | Pass | | | |
| | | Gravel | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|---|---------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Tuesday 7/9/2019 at approximately 10:00 AM, I, Inspector Scott Ramsey, conducted a routine field inspection and a follow up inspection at Caerus Couey 23 d Pad, at Location #334640 in Garfield County, Colorado.</p> <p>While there, I observed Normal production.</p> <p>Corrective actions were made as required on document #689300674</p> <p>This is a summary of inspection report.</p> | ramseys | 07/09/2019 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402106268 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876316 |
| 694900039 | 694900033 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876314 |