

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/12/2019

Submitted Date:

07/12/2019

Document Number:

695101009**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 307536 Beardslee, Tom 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1801 BROADWAY SUITE 350City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217796	WELL	PR	07/11/1998	GW	071-06575	MOUNTAIN LION 11-18	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment: PLUMBED TO SURFACE

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: TELEMETRY EQUIPMENT

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities				
Facility ID: 217796	Type: WELL	API Number: 071-06575	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Ditches	Fail			

Comment: PHOTO 3: AREA OF EROSION ON WEST SIDE OF ROW NORTH OF LOCATION TOWARD THE BOTTOM OF THE HILL.
 PHOTO 4: AREA OF EROSION ON EAST SIDE OF ROW NORTH OF LOCATION TOWARD THE BOTTOM OF THE HILL.
 PHOTO 3: AREA OF EROSION ON EAST SIDE OF ROW APP. 200 YARDS NORTH OF LOCATION.

Corrective Action: REPAIR EROSION AND REPAIR OR INSTALL BMP'S TO PREVENT EROSION AND COMPLY WITH RULE 1002.f.

Date: 08/12/2019

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402107532	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4877612
695101010	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4877592