

## Inspection Photos

Location Name: Razor 26J-2633L SWD Location ID 433131, Spill ID #465887

Inspection Date: 7/17/2019



**Photo 1 – Ditch on south side of location, looking east. Vegetation impacted by oil.**



**Photo 2 – Stormwater Detention on southwest corner of location, appears free from oil impacts.**



## Inspection Photos

Location Name: Razor 26J-2633L SWD Location ID 433131, Spill ID #465887

Inspection Date: 7/17/2019



**Photo 3 – Stormwater control ditch on south side of location.**



**Photo 4 – Area where spilled water and oil ran off location into stormwater control ditch on southside of location.**



## Inspection Photos

Location Name: Razor 26J-2633L SWD Location ID 433131, Spill ID #465887

Inspection Date: 7/17/2019



**Photo 5 – Stormwater control ditch on southside of location looking east.**



**Photo 6 – Stormwater control ditch continuing east of location, impacted by produced water and oil.**



## Inspection Photos

Location Name: Razor 26J-2633L SWD Location ID 433131, Spill ID #465887

Inspection Date: 7/17/2019



**Photo 7 – Stormwater control ditch on south side of location at southeast corner of location looking east. Produced water and oil exited location near southeast corner into ditch.**



**Photo 8 – Storm water control ditch east of location.**



## Inspection Photos

Location Name: Razor 26J-2633L SWD Location ID 433131, Spill ID #465887

Inspection Date: 7/17/2019



Photo 9 – Stormwater control pond east of location



Photo 10 – Stormwater control pond outlet box impacted by oil.



## Inspection Photos

Location Name: Razor 26J-2633L SWD Location ID 433131, Spill ID #465887

Inspection Date: 7/17/2019



**Photo 11 – Oily waste stockpiled on southeast corner of location.**



**Photo 12 – Standing crude oil near damaged tank battery.**

