

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/18/2019

Submitted Date:

07/19/2019

Document Number:

689802916**FIELD INSPECTION FORM**Loc ID 313194 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10548Name of Operator: HRM RESOURCES II LLCAddress: 410 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**15 Number of Comments10 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
Payne, Gina		gpayne@hrmres.com	
Reeves, Shane		shane@wolverineresources.com	
Pesicka, Conor		conor.pesicka@state.co.us	
Pape, Terry	970-768-5700	tpape@hrmres.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272296	WELL	SI	07/01/2017	GW	081-07184	ANDERSON 43-29	SI

**General Comment:****COGCC Inspection Report 689802916 Summary**

On Thursday 7/18/2019 at approximately 10:40, I, Inspector Emily Waldron, conducted a field inspection at HRM Resources II LLC Anderson 43-29, at 05-081-07184 in Moffat County Colorado.

The inspection was in response to complaint document number 200447765 and a follow up to inspection document number 689801804. While there, I observed a shut-in location.

During this inspection the following possible compliance issues were observed:

No wellhead sign. Install sign to comply with Rule 210.b by 12/26/2018.

No battery sign. Install sign to comply with Rule 210.b by 12/26/2018.

2 northern produced water tanks have been scribbled on and have "livestock water" and "stock water" written on the labels. See photo 14.

Install sign to comply with Rule 210.d by 9/18/2019.

Equipment mentioned in previous inspection continues to be stored on location. See photos 1-12. Comply with Rule 603.f by 1/28/2019.

Trash and debris present on location and beginning to migrate off location. See photos 1-12. Comply with Rule 603.f by 7/29/2019.

Non-reportable spills, stained soil on location. See photos 2-3. Comply with Rule 603.f, control and contain spills/releases and clean up per Rule 906.a. and properly treat or dispose of oily waste in accordance with 907.e by 7/29/2019.

4 - 2" steel risers not marked for abandonment or LOTO. Flowline risers not LO/TO or marked are considered unused equipment. See photos 15-16. Comply with Rule 603.f by 7/19/2019.

Weeds and vegetation growing on and in berm. See photo 13. Comply with Rule 603.f by 8/1/2019.

No current MIT on record or delinquent as required by Rule 326.

Form 10 document number 401476956, submitted 12/6/2017, On Hold to transfer from HRM Resources to Wolverine Resources.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 689802916.

### Location

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) or battery. No wellhead sign.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	12/26/2018
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible. 2 northern produced water tanks have been scribbled on and have "livestock water" and "stock water" written on the labels.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	09/18/2019
Type	BATTERY		
Comment:	Sign not posted or information inaccurate at well(s) or battery. No battery sign.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	12/26/2018

**Emergency Contact Number:**

Comment: 720-836-6046

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Trash and debris present on location and beginning to migrate off location.		
Corrective Action:	Comply with Rule 603.f.	Date:	07/29/2019
Type	UNUSED EQUIPMENT		
Comment:	4 - 2" steel risers not marked for abandonment or LOTO. Flowline risers not LO/TO or marked are considered unused equipment.		
Corrective Action:	Comply with Rule 603.f .	Date:	07/19/2019
Type	OTHER		
Comment:	Non-reportable spills, stained soil on location.		
Corrective Action:	Comply with Rule 603.f. Control and contain spills/releases and clean up per Rule 906.a. Properly treat or dispose of oily waste in accordance with 907.e.	Date:	07/29/2019
Type	STORAGE OF SUPL		
Comment:	Equipment mentioned in previous inspection continues to be stored on location.		
Corrective Action:	Comply with Rule 603.f.	Date:	01/28/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	#		
Comment:	Guy line anchors not marked.		
Corrective Action:	Install proper guy line markers per Rule 1003.a		Date: 08/05/2019

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Inadequate
Comment:	Weeds and vegetation growing on and in berm.			
Corrective Action:	Comply with Rule 603.f .			Date: 07/29/2019

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	300 BBLS	STEEL AST		40.795940,-107.851570
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Inadequate
Comment:	Weeds and vegetation growing on and in berm.			

Corrective Action:	Comply with Rule 603.f.	Date:	07/29/2019
--------------------	-------------------------	-------	------------

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	272296	Type:	WELL	API Number:	081-07184	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____									
Comment: <div>No current MIT on record or delinquent as required by Rule 326.</div>									
Corrective Action: <div></div> Date: _____									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No stormwater BMPs observed. No apparent soil migration; erosion or soil movement.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402116065	INSPECTION SUBMITTED	<a href="#">insp_402116065.pdf</a>
689802917	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885039">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885039</a>