

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/17/2019

Submitted Date:

07/21/2019

Document Number:

698600093**FIELD INSPECTION FORM**Loc ID 335737 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 90615Name of Operator: TUDEX PETROLEUM INCAddress: 2121 39TH AVE NE UNIT ECity: CALGARY State: AL Zip: T2E 6R7**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203258	WELL	PR	08/01/2014	OW	001-08767	HI-LAND 10-B	TA
203259	WELL	PR	05/01/2015	OW	001-08768	HI-LAND 10-G	TA

General Comment:

This is an orphaned well inspection. Inspection completed as site visit in preparation for rig moving onto location for well plugging and abandonment task.

Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.

See link at end of report for path to downloadable pictures.

Location

Lease Road:			
Type	Access		
comment:	Dirt and gravel two track off paved road.		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	COGCC contact sticker.		
Corrective Action:		Date:	

Good Housekeeping:			
Type	OTHER		
Comment:	55 gallon drum of Mobile Hydraulic 10W approximately 1/3 full inside wellhead fencing.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Chain link fencing topped with barb wire.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	Wellhead.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:	Located (6) marked anchors.		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 203258 Type: WELL API Number: 001-08767 Status: PR Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: Well is an Orphaned Well Program well. Valves at wellhead are closed and outlets bull plugged. Production equipment decommissioning previously completed.

Corrective Action: _____

Date: _____

Facility ID: 203259 Type: WELL API Number: 001-08768 Status: PR Insp. Status: TA

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No storm water issues noted at time of inspection.Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
The Tudex Plugging and Flow line Abandonment Project is underway. The Hi Land 10B and Hi Land 10G are (2) of the wells on the project to be plugged and abandoned. This is a site visit in preparation for moving rig onto the well location. Currently the location consisted of (2) wellheads, (6) anchors and chain link wellhead fencing. No issues were noted at time of inspection that would prevent rig and equipment from staging and performing plugging task. It was noted that 55 gallon drum 1/3 full of Mobile Hydraulic 10W is inside wellhead fencing.	stjohnw	07/21/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600094	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885334