

Inspection Photos

API: 05-071-09062

Operator: ARP PRODUCTION COMPANY
WAPITI OPERATING LLC

Inspection Date: 7/19/2019



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09062 | Date: 7/19/2019

Inspection Photos



Photo 1. There is List B noxious weeds growing along the main & access road to the location. (Musk thistle shown in photo) There were a few weeds wilting but most were not treated. Corrective action was not completed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09062 | Date: 7/19/2019

Inspection Photos



Photo 2. There is List B noxious weeds growing along the main & access road to the location. (Musk thistle shown in photo) There were a few weeds wilting but most were not treated. Corrective action was not completed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09062 | Date: 7/19/2019

Inspection Photos



Photo 3. Rock check dams were installed along the side of the access road to the location. Sediment has filled in the check dams or stormwater is flowing around. Corrective action was not performed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09062 | Date: 7/19/2019

Inspection Photos



Photo 4. The cut slope is not stabilized and erosion is occurring. No vegetation is establishing. Corrective action was not performed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09062 | Date: 7/19/2019

Inspection Photos



Photo 5. Rock rip/rap was installed at the end of the diversion ditch however, sediment has already filled in the diversion ditch from erosion of the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09062 | Date: 7/19/2019

Inspection Photos



Photo 6. Sediment has already filled in the diversion ditch from erosion of the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09062 | Date: 7/19/2019

Inspection Photos



Photo 9. There are noxious weeds (CMusk thistle) growing at the top of the cut slope. Corrective action was not completed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09062 | Date: 7/19/2019