

Inspection Photos

API: 05-071-06094

Operator: AMOCO PRODUCTION COMPANY

Inspection Date: 7/22/2019

Inspection Photos



Photo 1. Facing east toward the location from across the canyon. Reclamation has not been performed.

Inspection Photos



Photo 2. Facing south at the beginning of the access road.

Lat/Long:37.106763,-104.780271

Inspection Photos



Photo 3. Photo shows erosion along the access road. Access road has not been recontoured and reclaimed.

Inspection Photos



Photo 4. Further along the road. Access road has not been recontoured and reclaimed.

Inspection Photos



Photo 5. Culvert remains along the road. Erosion is occurring around the outlet.

Inspection Photos



Photo 6. Facing southeast toward the location. The pad has not been recontoured.

Inspection Photos



Photo 7. Facing towards the unstable vertical cut slope. Estimated to be 200' high.

Inspection Photos



Photo 8. Facing down the fill slope shows signs of erosion.

Inspection Photos



Photo 9. Facing toward the fill slope of the location.

Inspection Photos



Photo 10. There is significant signs of erosion off the southeast fill slope.

Inspection Photos



Photo 11. Facing north at the pad.

Inspection Photos



Photo 12. Facing towards the unstable vertical cut slope. Estimated to be 200' high.

Inspection Photos



Photo 13. Facing east toward the location from across the canyon. The fill slope is not stabilized and shows signs of erosion. Location not recontoured.