

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/19/2019

Submitted Date:

07/22/2019

Document Number:

679704802

FIELD INSPECTION FORM

Loc ID 314522 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 82440
Name of Operator: STEHLE OIL COMPANY
Address: P O BOX 1577
City: CRAIG State: CO Zip: 81626

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	
Pesicka, Conor	970-415-0789	conor.pesicka@state.co.us	
Stehle, Cary	970-824-6909	carystehle@gmail.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228908	WELL	SI	09/08/2014	OW	103-05906	PINNACLE UNIT 12-30	TA

General Comment:

[COGCC Inspection Report Summary.](#)

On 7-19-2019 at approximately 12:30, inspector Rick Moran, conducted a follow up inspection at Stehle Oil Company well Pinnacle Unit 12-30 in Rio Blanco county of FIR documents:

- 1) 689801592 dated 8-28-2018.
- 2) 673402281 dated 7-24-2015.
- 3) 673400953 dated 8-5-2014.
- 4) NOAV 401781684 for MIT dated 10-4-2018.

The following compliance issues were identified as resolved:

- 1) Leaking gas at well head.

The following compliance issues were observed as uncompleted:

- 1) Tank label. Photo 5. Complete by 10-26-2018.
- 2) Battery sign. Photo 5. Complete by 10-26-2018.
- 3) Stained soil. Photos 7, 8, 9, 10. Complete by 9-28-2018.

Additional compliance issues were identified:

- 1) MIT.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679704802.

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	Sign not posted.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	10/26/2018
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Label is not present.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/26/2018

Emergency Contact Number:			
Comment:	970-824-6909 or 970-629-1007		
Corrective Action:		Date:	_____

Overall Good:

Spills:			
Type	Area	Volume	
Crude Oil			
Comment:	Stained soil at: tank berm, well head, laid down tubing, and pump jack exhaust.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a Contact COGCC EPS staff.	Date:	09/28/2018

In Containment: No
 Comment: _____
 Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	#		
Comment:	Tubing & rods laid down on ground next to pump jack.		
Corrective Action:		Date:	

Type: Ancillary equipment	# 1	
Comment:	Propane tank.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	400 BBLs	STEEL AST		40.201500,-107.092500
Comment:	Tank is open to atmosphere at base. Photo 3.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 228908 Type: WELL API Number: 103-05906 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last recorded production July 2014. MIT witnessed on 7-27-2018 at which time the test failed (FIR document 689801355). No MIT documentation on file indicating a successful MIT.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679704803	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885415