

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/16/2019

Submitted Date:

07/16/2019

Document Number:

687905187**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 325151 Stewart, Joseph 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96735Name of Operator: WILLIFORD RESOURCES, L.L.C.Address: 6506 S LEWIS AVE STE 102City: TULSA State: OK Zip: 74136**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|----------------|------------------------------|-------------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| Stevens, Glenn | (970) 749-0192 | glennstevens@centurylink.net | |
| Callahan, Linda | (918) 712-8828 | lcallahan3@swbell.net | e-mail receipient |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 214134 | WELL | PR | 04/01/2019 | OW | 067-05446 | DYE-HARD 1 | PR |

General Comment:

Site inspection with photos at the end of this inspection report. This inspection does not allieviate prior corrective actions from previous inspections.

| Location | | | | |
|--|---|--------|--|------------------|
| Lease Road: | | | | |
| Type | Access | | | |
| comment: | Two-track dirt road. | | | |
| Corrective Action | L | | | Date: |
| Overall Good: <input type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | TANK LABELS/PLACARDS | | | |
| Comment: | Labels and placards posted on tank and are beginning to peel off. | | | |
| Corrective Action: | | | | Date: |
| Type | WELLHEAD | | | |
| Comment: | Sign posted at wellhead. | | | |
| Corrective Action: | | | | Date: |
| Emergency Contact Number: | | | | |
| Comment: | Contact information and 911 posted on sign. | | | |
| Corrective Action: | | | | Date: _____ |
| Good Housekeeping: | | | | |
| Type | WEEDS | | | |
| Comment: | Weeds around pumpjack. | | | |
| Corrective Action: | Control weeds per Rule 603.f. | | | Date: 07/26/2019 |
| Overall Good: <input type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: _____ | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Equipment: | | | | |
| Type: Ancillary equipment | # 1 | | | corrective date |
| Comment: | Stained soil around wellhead. | | | |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. | | | Date: 08/16/2019 |
| Type: Pump Jack | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Prime Mover | # 1 | | | |
| Comment: | Electric driven motor powering pumpjack. | | | |
| Corrective Action: | | | | Date: |
| Type: Flow Line | # 1 | | | |
| Comment: | 1-2" flowline from wellhead to Crude oil tank. | | | |
| Corrective Action: | | | | Date: |

| | | |
|--------------------------|-----|-------|
| Type: Deadman # & Marked | # 4 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| | | | | | |
|--------------------|---|----------|-----------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 1 | 300 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|-----|-------|
| Yes/No | YES | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 214134 | Type: | WELL | API Number: | 067-05446 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|--------------------------------------|
| Compaction | Pass | Compaction | Pass | | | |
| | | | | Material Handling And Spill Prevention | Pass | Spill prevention for 55 gallon drum. |
| Ditches | Pass | Culverts | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------------|---|
| 402111709 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4880624 |
| 687905193 | Weeds around pumpjack. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4880611 |
| 687905194 | Stained soil around wellhead. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4880612 |