

Inspection Photos
Location Name: Maylon Scow Pilcher #1
API: 05-083-06418



Location ID #393155 with 200 bbl. AST.



Corroded bottom seam and stained soil.

Inspection Photos
Location Name: Maylon Scow Pilcher #1
API: 05-083-06418



Track hoe excavating containment area.



Containment area lined with plastic sheeting.

Inspection Photos
Location Name: Maylon Scow Pilcher #1
API: 05-083-06418



Load out valve opened.



Fluids drained from AST.

Inspection Photos
Location Name: Maylon Scow Pilcher #1
API: 05-083-06418



AST knocked over by track hoe.



Area where AST had been.

Inspection Photos
Location Name: Maylon Scow Pilcher #1
API: 05-083-06418



Corrosion along bottom seam of AST.



Excavating impacted material.

Inspection Photos
Location Name: Maylon Scow Pilcher #1
API: 05-083-06418



Sample location from eastern portion of excavation.



Sample location from western portion of excavation.

Inspection Photos
Location Name: Maylon Scow Pilcher #1
API: 05-083-06418



Flushing residue from AST.



Track hoe demolishing AST.

Inspection Photos
Location Name: Maylon Scow Pilcher #1
API: 05-083-06418



AST crushed into size to transport.



AST loaded onto flat bed trailer.

Inspection Photos
Location Name: Maylon Scow Pilcher #1
API: 05-083-06418



Excavated area backfilled with clean fill.



Project area returned to contour.