

**Inspection Photos**  
**Operator: Enduring Resources**  
**Location/API #: 067-08400**  
**Date: 7-18-2019**



Photo 1. View of southern project area from the southwestern edge facing eastward. Hundreds of musk thistles (*Carduus nutans*) are blooming and need immediate control.



Photo 2. Closeup view of musk thistles within the southern project area.