

Inspection Photos

Operator: Enduring Resources
Location/API #: 067-07467
Date: 7-18-2019



Photo 1. View of northern project area from the northeastern edge facing westward.



Photo 2. View of wattle full of sediment and erosional down-cutting downstream from culvert near well pad entrance.



Photo 2. View of rilling and erosional down-cutting of bare soils along access road.



Photo 3. View of damaged culvert full of sediment and erosional rilling around culvert near the well pad entrance.