

Inspection Photos
Location Name: SUMMERS 21-19 TR
API#: 05-071-09149
INSP. #: 695101108



Colorado Oil & Gas Conservation Commission
37.24822, -104.71586, 2163.0m, 132°
2019/07/23 08:38:45



Colorado Oil & Gas Conservation Commission
37.24839, -104.71603, 2207.0m, 254°
2019/07/23 08:38:40

PHOTO 1: WELLHEAD

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: SUMMERS 21-19 TR

API#: 05-071-09149

INSP. #: 695101108



PHOTO 3: AREA OF IMPACTED SOIL INSIDE COMPRESSOR HOUSE APPEARS TO BE OIL STAINING FROM COMPRESSOR. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 8/23.19.

PHOTO 4: VALVE ON ENGINE SKID WAS LEAKING THERE IS AN AREA OF IMPACTED SOIL NEAR LEAKING VALVE. Increase frequency of maintenance and self inspection schedule of equipment to prevent impacting surface materials and mixing of wastes with precipitation. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. CA DATE 8/23/19.

Inspection Photos
Location Name: SUMMERS 21-19 TR
API#: 05-071-09149
INSP. #: 695101108



PHOTO 5: GUY LINE ANCHOR MARKER IS DOWN. REINSTALL GUY LINE ANCHOR MARKER. COMPLY WITH RULE 1003. CA DATE 8/23/19.

PHOTO 6: Vacuum pump observed on well without COGCC approval. Provide COGCC with documentation showing approval of use of vacuum pump. CA DATE 8/8/19.