

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/18/2019

Submitted Date:

07/18/2019

Document Number:

687905226**FIELD INSPECTION FORM**Loc ID 306919 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Labowskie, Steve		steve.labowskie@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277750	WELL	PR	05/01/2018	GW	067-09047	DRY CREEK FEDERAL 2	PR

General Comment:[Site inspection with photos at the end of this report.](#)

Location				
Lease Road:				
Type	Access			
comment:	Gravel road access.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Sign posted at entrance to location.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Labels/placards posted on tank.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Contact information posted on sign.			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Cattle panels around wellhead.			
Corrective Action:				Date:
Type	SEPARATOR			
Comment:	Cattle panels around separator and produced water tank.			
Corrective Action:				Date:
Equipment:				
Type: Ancillary equipment	# 1			corrective date
Comment:	Wellhead has stained gravel/soil around it.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: 08/18/2019
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:
Type: Prime Mover	# 1			
Comment:	Electric VFD drive motor with MCC			
Corrective Action:				Date:

Type: Vertical Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:	On produced water tank vent.	
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	PVC bradenhead access.	
Corrective Action:		Date:
Type: Flow Line	# 5	
Comment:	2-3" flowlines from wellhead to separator. 1-2" flowline from separator blowdown to produced water tank. 1-2" flowline from separator dump valve to offsite produced water gathering system. 1-3" flowline from separator to offsite dogleg.	
Corrective Action:		Date:
Type: Progressive Cavity	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Double wall tank with level control equipment and no secondary containment.			
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: 277750	Type: WELL	API Number: 067-09047	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing.			
Corrective Action:				Date:

--	--	--	--	--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gradient Terraces	Pass					
Ditches	Pass	Ditches	Pass			
Gravel	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			
Compaction	Pass	Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402114748	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4883791
402114750	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4883793
687905237	Location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4883772
687905238	Stained soil/gravel around wellhead.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4883773