

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/19/2019

Submitted Date:

07/19/2019

Document Number:

687905258**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 320857 Stewart, Joseph 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**20 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205245	WELL	PR	02/01/2001	GW	007-06123	SEIBEL A 1	PR
442577	WELL	PR	01/05/2016	LO	007-06317	Seibel A 2	PR

General Comment:[Site inspection with photos at the end of this report.](#)

LocationOverall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Labels/placards posted on tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Signs posted at entrance to location.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Emergency contact information posted on signs.

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Wellhead valve sitting on ground by pumpjack.		
Corrective Action:	Remove unused equipment per Rule 603.f.	Date:	08/29/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Cattle panels around wellheads and pumpjacks/LRP's.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Cattle panels around separators, meter houses and piping tie-in points.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	*1-1" domestic gas tap from separator to offsite natural gas powered engine for center pivot irrigation system. Currently open and in use.		
Corrective Action:		Date:	
Type: Flow Line	# 5		

Comment:	Wellhead #1: 1-3" flowline from wellhead to separator. 1-2" flowline from separator dump valve to produced water tank. 1-2" flowline from separator to meter house. 1-2" flowline from meter house to valve cluster tie-in point @6" rack to offsite. 1-1" flowline from separator to heated tank fuel gas.				
Corrective Action:				Date:	
Type: Pump Jack		# 2			
Comment:	Pumpjack and Linear rod pump.				
Corrective Action:				Date:	
Type: Vertical Heated Separator		# 2			
Comment:					
Corrective Action:				Date:	
Type: Prime Mover		# 2			
Comment:	Electric VFD driven motors on pumpjack/LRP with MCC's.				
Corrective Action:				Date:	
Type: Bird Protectors		# 3			
Comment:	(1) on heated tank, (2) on separator stacks.				
Corrective Action:				Date:	
Type: Bradenhead		# 2			
Comment:	PVC bradenhead access.				
Corrective Action:				Date:	
Type: Ancillary equipment		# 2			
Comment:	Wellheads.				
Corrective Action:				Date:	
Type: Flow Line		# 7			
Comment:	Wellhead#2: 1-4" flowline from wellhead to separator. 1-2" flowline from wellhead to separator. 1-2" flowline from separator dump valve to produced water tank. 1-4" flowline from separator to valve cluster tie-in point @6" rack. 1-2" flowline from produced water tank to electric transfer pump. 1-2" flowline from electric transfer pump to offsite produced water gathering system. 1-2" flowline from offsite gathering system to produced water tank.				
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	HEATED STEEL AST		,
Comment:	Produced water tank has electric transfer pump to move produced water offsite.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:		
Corrective Action:		Date: <input type="text"/>
<u>Venting:</u>		
Yes/No	NO	
Comment:		
Corrective Action:		Date: <input type="text"/>
<u>Flaring:</u>		
Type		
Comment:		
Corrective Action:		Date: <input type="text"/>

Inspected FacilitiesFacility ID: 205245 Type: WELL API Number: 007-06123 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Facility ID: 442577 Type: WELL API Number: 007-06317 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Culverts	Pass			
Ditches	Pass	Ditches	Pass			
Berms	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402116063	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885060
687905268	Unused equipment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885035
687905269	Location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885036
687905270	Location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885037
687905271	Domestic gas tap.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885038