

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/18/2019

Submitted Date:

07/19/2019

Document Number:

696600343**FIELD INSPECTION FORM**
 Loc ID 312548 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Graves, Jim		mrinc20@qwestoffice.net	
Kellerby, Shaun		shaun.kellerby@state.co.us	<a href="#">All Inspections</a>
Ried, Jordan	970-563-400	maralextechjr@gmail.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221891	WELL	PR	10/01/2018	GW	077-08493	USA 1-18 JC	TA

**General Comment:**

This is a follow up from inspection dated 4/24/2019 Doc#675002210 Required Corrective Action (s) items noted in previous inspections have not all been satisfied.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	All signage corrective actions have been made		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds growing on location		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	PIT		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Type	WELLHEAD			
Comment:				
Corrective Action:			Date:	
Type	SEPARATOR			
Comment:				
Corrective Action:			Date:	

**Equipment:**

			corrective date
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	#		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 0		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:	Disconnected at time of inspection.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLS	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Sufficient	Adequate
Comment:	Weeds growing in containment, Locations single well is TA and tank is not used at time of inspection. Earth Berm needs maintenance			
Corrective Action:	Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).			Date: 04/23/2019

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

--

**Inspected Facilities**Facility ID: 221891 Type: WELL API Number: 077-08493 Status: PR Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Well is shut in. Last production posted: 5/19  
Separator is not operable.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Compaction	Pass			
Gravel	Pass					
Compaction	Pass					

Comment: At time of inspection stormwater erosion appears to be controlled.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type: Blowdown

Lined: NO

Pit ID:

Lat:

Long:

Reference Point: \_\_\_\_\_

Other: \_\_\_\_\_

Length: \_\_\_\_\_

Width: \_\_\_\_\_

**Lining:**

Liner Type:

Liner Condition:

Comment:

There are two pits on location. . Both earth, no liner. No use of pits at time of inspection. Pits are dry. No Form 15 for pits have been filed.

Corrective Action

Submit an eForm 15 Pit Report to update COGCC records with current information.

Date: 08/05/2019

**Fencing:**

Fencing Type: Wildlife

Fencing Condition: Adequate

Comment:

Corrective Action

Date:

**Netting:**

Netting Type: Mesh

Netting Condition: Good

Comment:

Two pits on location. One has wire mesh for netting, the other hasn't any netting.

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

**COGCC Comments**

Comment	User	Date
<p>On (Thursday) (7/18/19) at approximately (1253),  I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field Re-Inspection)  at (Maralex) (USA 1-18 JC), (API #077-08493) in (Mesa) Colorado.  While there, I observed (A Production Operation only.)  During this inspection, compliance issues were observed:  Corrective actions from previous inspection have not all been made:  Containment berm around tank needs maintenance  No form 15 for pits has been filed.  (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed compliance issue.  A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC Rules  (if correction actions are identified)  This is a summary of inspection report.</p>	wentzeld	07/18/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402115122	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4884194">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4884194</a>
696600344	Inspection 696600343 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4884180">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4884180</a>