

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/18/2019

Submitted Date:

07/19/2019

Document Number:

696600345**FIELD INSPECTION FORM**Loc ID 312655 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Graves, Jim		mrinc20@qwestoffice.net	
Ried, Jordan	970-563-400	maralextechjr@gmail.com	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
Colby, Lou		lou.colby@state.co.us	All Reclamation

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222090	WELL	TA	10/24/2013	GW	077-08692	SULFUR GULCH 9-98-28 1	PA

General Comment:

This is a follow up from inspection dated 9/13/18 Doc# 689401604 Required Corrective Action (s) items noted in previous inspections have been satisfied. Well Is Plugged and abandoned.
Form 4 file 4/20/15 doc #400827915 for NOTICE OF CONTINUED TEMPORARILY ABANDONED STATUS is last information filed.

Inspected Facilities

Facility ID: 222090 Type: WELL API Number: 077-08692 Status: TA Insp. Status: PA

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Plugged and abandoned. Only a surface marker remains.
No MIT on file no current form 4 on file.

Corrective Action: Well must have a successful mechanical integrity test performed or plugged as directed
by Rule 319 b (3)
10 days to contact COGCC Engineering Group

Date: 07/29/2019

COGCC Comments

Comment	User	Date
<p>On (Thursday) (7/18/19) at approximately (1353), I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field Re-Inspection) at (Maralex) (Sulfur Gulch 9-98-28 1), (API #077-08692) in (Mesa) Colorado. While there, I observed (Abandoned well surface marker.) During this inspection compliance issues were observed: No form filed other than a form 4, for continued TA status on 4/20/15 doc #400827915 No record of a current form 4 or MIT filed. (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC Rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	07/18/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402115127	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4884198
696600346	Inspection 696600345 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4884181