

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/18/2019

Submitted Date:

07/19/2019

Document Number:

694500112

**FIELD INSPECTION FORM**
 Loc ID 313000 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10407

Name of Operator: ANTLER ENERGY LLC

Address: PO BOX 104

City: BAGGS State: WY Zip: 82321

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		antlerenergy@yahoo.com	
Clay, Evans		clay@antler-energy.com	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
100408	PIT	AC			-	PTASYNSKI 1X TANK BATTERY	EI
223250	WELL	PR	09/22/1985	OW	081-06614	PTASYNSKI 1X	EI

**General Comment:**

On 6/18/2019, COGCC staff, Kris Neidel and Alex Fischer inspected the Ptasynski 1-x well pad and adjacent facilities; treater, tank battery, well, pit, land treatment area. The pit on location appears to have been closed as a part of REM project #7632. The pit has not been backfilled and should be physically closed. Inspection document 685100051, dated 6/30/2018, required that a form 27 for the land treatment area, as of this inspection, NO information has been received. It appears that the a land treatment project is part of project number 7362, please submit the update on a eForm 27 with this project number. At the time of this inspection the well was SI, the land treatment area was mostly free of vegetation there was what appeared to be weathered oil in the treatment area. The wellhead had a weather oil stained soil, there was a small, ongoing drip from the tree. The pit, facility 100408 had an open excavation that was partially fenced, no hydrocarbon was observed. The pumpjack motor had oil staining on the motor and inside the pumphouse on the ground. Antler Energy should ensure shut in wells are not leaking in any way. Antler Energy shall provided information that was requested in 2016. See attached photos. Operator should ensure actions required from previous inspections are completed, this inspection address specific Environmental items are documented here and does not necessary address previous required action required.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

<b>Good Housekeeping:</b>		
Type	TRASH	
Comment:	trash in pumphouse	
Corrective Action:	remove trash and unused equipment. Comply with Rule 603.f .	Date: 08/02/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
PW/CO	WELLHEAD	<= 1 bbl	
Comment:	stained soil at wellhead, active drip on wellhead (very small drip)		
Corrective Action:	prevent any unintended release. remove stained soil.		Date: 08/19/2019
Lube Oil	Pump Jack	<= 1 bbl	
Comment:	lube oil on pumjack and in pumphouse.		
Corrective Action:	remove stained soil. prevent future leaking.		Date: 08/19/2019

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	100408	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI
Facility ID:	223250	Type:	WELL	API Number:	081-06614	Status:	PR	Insp. Status:	EI

**Environmental****Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)	
Oily Soil	Land Treatment	Inadequate	40.915190	-108.322798
Comment	a land treatment area is existing, no Remediation project has been created to document this project. The soil had very little vegetative growth. It appeared to have not been tilled this season. see attached photos for location of land treatment.			
Corrective Action	Inspection document 685100051, dated 6/30/2018, required that a form 27 for the land treatment area, as of this inspection, NO information has been received. Antler Energy shall provided information that was requested in 2016.			Date: 07/26/2019

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): Comment: Pilot:  Wildlife Protection Devices (fired vessels): **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402116133	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885243">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885243</a>
694500124	photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885241">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885241</a>