

Inspection Photos
Location Name: UPRR 23 Pan Am D 2
Location ID: 319939



Pic 1



Pic 2 stained soil

Inspection Photos
Location Name: UPRR 23 Pan Am D 2
Location ID: 319939



Pic 3 stained soil by motor, no BMP for chemical tank



Pic 4 unused guard

Inspection Photos
Location Name: UPRR 23 Pan Am D 2
Location ID: 319939



Pic 5



Pic 6

Inspection Photos
Location Name: UPRR 23 Pan Am D 2
Location ID: 319939



Pic 7



Pic 8 stained soil/mechanical issue in separator house

Inspection Photos
Location Name: UPRR 23 Pan Am D 2
Location ID: 319939



Pic 9



Pic 10 mechanical issue with valve on oil tank.