

Laramie Energy LLC
API # 05-077-08699
Inspection # 696600406



Battery sign at entrance of location.

Laramie Energy LLC
API # 05-077-08699
Inspection # 696600406



Photo #1 Photo at entrance of S side of location .



Photo #2 Photo at entrance of West location side of location

Laramie Energy LLC
API # 05-077-08699
Inspection # 696600406



Photo #3 Photo of tank battery



Photo #4 photo at wellheads

Laramie Energy LLC
API # 05-077-08699
Inspection # 696600406



Photo #5 Photo of sediment moving south across location



Photo # 6 Photo of sediment moving south across location

Laramie Energy LLC
API # 05-077-08699
Inspection # 696600406



Photo #7 Photo of sediment moving south across location



Photo #8 Photo of sediment moving south across location

Laramie Energy LLC
API # 05-077-08699
Inspection # 696600406



Photo #9 Sediment moving off location on the south side of tank battery, choking out possible vegetation



Photo #10 Location has lost compaction by wellhead and tank battery

Laramie Energy LLC
API # 05-077-08699
Inspection # 696600406



Photo #11 Photo of BMP that was recently put in place, allows erosions sediment to move around the waddle, letting sediment move south off location, choking out vegetation.



Photo #12 Photo of BMP that was recently put in place to stop erosion, allows erosions sediment to move around the waddle, letting sediment move south off location, choking out vegetation.