

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/29/2019

Submitted Date:

07/30/2019

Document Number:

696600406**FIELD INSPECTION FORM**
 Loc ID 312656 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
Clark, Chris		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222097	WELL	PR	06/01/2017	GW	077-08699	WAGON TRACK FEDERAL 12-14	PR

General Comment:

This is a follow up from inspection dated 6/27/2019 Doc# 696600211 Required Corrective Action (s) items noted in previous inspections have not been satisfied.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Battery sign at entrance. 1-800-891-6191		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 0		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		,
Comment:	80 bbls				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: 222097	Type: WELL	API Number: 077-08699	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing Well			
Corrective Action:				Date:

--	--	--	--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Compaction	Fail					
Waddles	Fail					
Gravel	Pass					

Comment: Stormwater erosion not being controlled on the location at this time.
Stormwater issues were still observed:
BMP needs installed to prevent erosion sediment from moving onto, across and back off location. See photos 5,6,7,8
Erosion Sediment on south side of location behind tanks, is moving of location choking vegetation. See photo #9
Location has lost compaction See photo #10
Sediment moving off location, BMP or waddel installed, allows erosion sediment to move around it, allowing sediment to choke vegetation. See photos 11 and 12.

Corrective Action: **Install or repair required BMPs per Rule 1002.f.**

Date: 08/30/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On (Monday) (7/29/19) at approximately (1325), I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field Re-Inspection) at (Laramie) (Wagon Track Fed 12-14), (API #077-08699) in (Mesa) Colorado. While there, I observed (A Production Operation only.) During this inspection compliance issues were observed: Stormwater issues were observed: BMP needs installed to prevent erosion sediment from moving onto, across and back off location. See photos 5,6,7,8 Erosion Sediment on south side of location behind tanks, is moving of location choking vegetation. See photo #9 Location has lost compaction See photo #10 Sediment moving off location, BMP or waddel installed, allows erosion sediment to move around it, allowing sediment to choke vegetation. See photos 11 and 12. (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed. compliance issue. . A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC Rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	07/29/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
696600407	Inspection 696600406 photos	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4894367