

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/24/2019

Submitted Date:

07/24/2019

Document Number:

695101114

FIELD INSPECTION FORM

Loc ID 309542 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1801 BROADWAY SUITE 350
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299602	WELL	PR	07/13/2011	GW	071-09674	Anson 12-19	PR

General Comment:

[THIS IS A SOUND STUDY BASED FROM A COMPLAINT.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Equipment	Volume	corrective date
Compressor	# 1		
Comment:	Vacuum pump observed on well without COGCC approval.		
Corrective Action:	IMMEDIATELY STOP PRODUCING WELL ON A VACUUM. DO NOT OPERATOR VACUUM EQUIPMENT (COMPRESSOR) WITHOUT COMPLETE COMPLIANCE WITH RULE 331 AND 802.		Date: <u>07/24/2019</u>

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 299602 Type: WELL API Number: 071-09674 Status: PR Insp. Status: PR**Complaint**

Comment: STEVE LABOWSKIE PERFORMED A SOUND STUDY STARTING @ APPROXIMATELY 7:30 A.M. FOR 20 MINUTES. WIND SPEED APP. 0-3 MPH. TEMP 50*
SOUND METER SET @ 70' FROM COMPRESSOR EXHAUST results are 65.3 AVERAGE db (a) calc. to 51.3 db (a) @ 350'.
NO SOUND ABATEMENT OBSERVED FOR COMPRESSOR @ TIME OF INSPECTION.

Corrective Action: **Comply with Rule 802. Identify and install control measures.**Date: 07/25/2019**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402121302	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889779
695101115	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889773
695101116	SOUND SURVEY DATA	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889774