

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/30/2019

Submitted Date:

07/31/2019

Document Number:

694900118**FIELD INSPECTION FORM**

Loc ID 439173	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 23 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
439165	WELL	PR	06/20/2016	OW	045-22510	Youberg RU 532-7	PR
439166	WELL	PR	08/03/2015	OW	045-22511	Youberg RU 444-7	PR
439167	WELL	PR	08/31/2015	OW	045-22512	Youberg RU 534-7	PR
439168	WELL	PR	08/01/2016	OW	045-22513	Youberg RU 433-7	PR
439169	WELL	PR	06/20/2016	OG	045-22514	Youberg RU 33-7	PR
439171	WELL	PR	07/13/2016	OW	045-22516	Youberg RU 543-7	PR
439172	WELL	PR	09/30/2015	OW	045-22517	Youberg RU 434-7	PR
439174	WELL	PR	08/31/2015	OW	045-22518	Youberg RU 544-7	PR
439175	WELL	PR	08/01/2016	OW	045-22519	Youberg RU 533-7	PR
439176	WELL	PR	07/13/2016	OW	045-22520	Youberg RU 333-7	PR
439177	WELL	PR	06/20/2016	OG	045-22521	Youberg RU 443-7	PR
439178	WELL	PR	07/13/2016	OW	045-22522	Youberg RU 44-7	PR
439179	WELL	PR	08/01/2016	OW	045-22523	Youberg RU 344-7	PR

General Comment:

CA's as specified as required were met per inspection #689302204

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	chemical tank has no labels see photo		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	08/30/2019

Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:			
Type	TRASH		
Comment:	used insulation in containment. see photo		
Corrective Action:	Comply with Rule 603.f .	Date:	08/13/2019

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	livestock fence		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	hog panel		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	hog panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 13		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	chemical tanks at well heads		
Corrective Action:		Date:	
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:		Date:	

Type: Other	# 1		
Comment:	portabe meter house		
Corrective Action:		Date:	
Type: Plunger Lift	# 13		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities						
Facility ID:	439165	Type:	WELL	API Number: 045-22510	Status: PR	Insp. Status: PR
Producing Well						
Comment:	plunger lift					
Corrective Action:						Date:
Facility ID:	439166	Type:	WELL	API Number: 045-22511	Status: PR	Insp. Status: PR
Producing Well						
Comment:	plunger lift					
Corrective Action:						Date:
Facility ID:	439167	Type:	WELL	API Number: 045-22512	Status: PR	Insp. Status: PR
Producing Well						
Comment:	plunger lift					
Corrective Action:						Date:
Facility ID:	439168	Type:	WELL	API Number: 045-22513	Status: PR	Insp. Status: PR
Producing Well						
Comment:	plunger lift					
Corrective Action:						Date:
Facility ID:	439169	Type:	WELL	API Number: 045-22514	Status: PR	Insp. Status: PR
Producing Well						
Comment:	plunger lift					
Corrective Action:						Date:
Facility ID:	439171	Type:	WELL	API Number: 045-22516	Status: PR	Insp. Status: PR
Producing Well						
Comment:	plunger lift					
Corrective Action:						Date:
Facility ID:	439172	Type:	WELL	API Number: 045-22517	Status: PR	Insp. Status: PR
Producing Well						
Comment:	plunger lift					
Corrective Action:						Date:
Facility ID:	439174	Type:	WELL	API Number: 045-22518	Status: PR	Insp. Status: PR
Producing Well						
Comment:	plunger lift					
Corrective Action:						Date:

Facility ID:	439175	Type:	WELL	API Number:	045-22519	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [plunger lift](#)

Corrective Action:

Date:

Facility ID:	439176	Type:	WELL	API Number:	045-22520	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [plunger lift](#)

Corrective Action:

Date:

Facility ID:	439177	Type:	WELL	API Number:	045-22521	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [plunger lift](#)

Corrective Action:

Date:

Facility ID:	439178	Type:	WELL	API Number:	045-22522	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [plunger lift](#)

Corrective Action:

Date:

Facility ID:	439179	Type:	WELL	API Number:	045-22523	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [plunger lift](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Ditches				
		Check Dams				
		Retention Ponds				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 7/30/19 at approximately 12:30 PM, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP RU 44-7, at location #439173 in Garfield County, Colorado. While there, I observed normal production operations. C/A from last inspection looked to be satisfied.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Some old insulation in the tank battery.</p> <p>And a chemical tank at the wells unmarked.</p> <p>Refer to photograph of observed compliance issue.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if corrective actions are identified).</p> <p>This is a summary of inspection report.</p>	ramseys	07/30/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900121	694600118	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4896439