

# Inspection Photos

API: 05-073-06478

Operator: NIGHTHAWK PRODUCTION

Inspection Date: 7/25/2019



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06478 | Date: 7/25/2019

## Inspection Photos



**Photo 1.** Facing south at the reclaimed access road. Vegetation is well established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06478 | Date: 7/25/2019

## Inspection Photos



**Photo 2.** Perimeter fence remains around the location and is in disrepair.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06478 | Date: 7/25/2019

## Inspection Photos



**Photo 3.** Facing south at the location. Vegetation is well established at this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06478 | Date: 7/25/2019

## Inspection Photos



**Photo 4.** Facing north at the location. Vegetation is well established at this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06478 | Date: 7/25/2019

## Inspection Photos



**Photo 5.** There is a bare are at the east side of the location. Approximately 50 ft. x 30 ft..



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06478 | Date: 7/25/2019

## Inspection Photos



**Photo 6.** Vegetation consists primarily of Ely ely.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06478 | Date: 7/25/2019

## Inspection Photos



**Photo 7.** Facing toward the surrounding reference area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06478 | Date: 7/25/2019