

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/30/2019

Submitted Date:

07/31/2019

Document Number:

696101191**FIELD INSPECTION FORM**Loc ID 418211 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 83555Name of Operator: SUNBURST INCAddress: P.O. BOX 140266City: EDEGEWATER State: CO Zip: 80214**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**17 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mazotti, Joe		ogp-co@comcast.net	<a href="#">Regulatory Consultant</a>
Ash, Margaret		margaret.ash@state.co.us	
Jackson, Jay		sun1045@aol.com	
Carnes, Greg		gcarnes@kc.rr.com	
,		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Kirschner, Steven		steven.kirschner@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418212	WELL	AB	08/20/2013	OW	123-31853	Smuggler 16-10-62	SI

**General Comment:**

This is a WELL & BATTERY Inspection.

Wells: 1 well: Shut-In | SI.

Facility / Battery: ALL equipment appears shut-down.

Follow-up to Field Inspection Report Doc #691200488 dated 09/24/2018.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	<p>Prior insp: Oily Waste. Open 5-gallon bucket approximately half full of oily fluid. Refer to Rule 907.e for guidance. Properly treat or dispose of oily waste in accordance with Rule 907.e. Corrective Action date: 10/25/2018.</p> <p>This insp: * Open 5-gallon bucket approximately half full of oily fluid has been removed. See photos #5, 6.</p>		
Corrective Action:		Date:	
Type	WEEDS		
Comment:	<p>Prior insp: Weeds in and around tank berms treater, pumpjack and engine shed. Refer to Rule 603.f. Remove, manage, &amp; control weeds in tank berms. treater, pumpjack and engine shed. Comply w/ Rule 603.f. Corrective Action date: 10/05/2018</p> <p>This insp: * Weeds remain in and around tank berms, treater, pumpjack and engine shed. See photos #3, 4. Corrective Action date: 10/05/2018. Original Corrective Action date remains applicable. See photos #1, 2, 9-12.</p>		
Corrective Action:	Remove, manage, & control weeds in tank berms. treater, pumpjack and engine shed. Comply w/ Rule 603.f.	Date:	10/05/2018
Overall Good: <input type="checkbox"/>			

<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	PUMP JACK			
Comment:	Iron rod / mesh panel			
Corrective Action:			Date:	
<b>Equipment:</b>				corrective date
Type: Ancillary equipment	# 3			
Comment:	1: propane tank 2: drums motor oil in engine house in spill tray.			
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:	Gas meter run valves are shut at both upstream & downstream ends.			
Corrective Action:			Date:	
Type: Vertical Heater Treater	# 1			
Comment:				
Corrective Action:			Date:	
Type: Emission Control Device	# 1			
Comment:	Controls crude oil tanks VOCs. Pilots: OFF   Shut-down.			
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:	Prior insp: Bradenhead does NOT appear plumbed to surface. Mechanical Conditions. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Corrective Action date: 10/25/2018.  This insp: * Bradenhead NOW appears plumbed to surface. See photos #3, 4.			
Corrective Action:			Date:	
Type: Flare	# 1			
Comment:	Flare not in operation. Inlet valve is shut.			
Corrective Action:			Date:	
Type: Bird Protectors	# 2			
Comment:				
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:				

Corrective Action:				Date:	
Type: Prime Mover	# 1				
Comment:	<p>Gas engine.</p> <p>Prior insp: Gas Engine &amp; wellsite. Stained soil around base of gas engine, exhaust, and near wellhead. Mechanical Conditions (30 days). Refer to Rule 605.d for guidance. Corrective Action date: 10/25/2018.</p> <p>This insp: * Stained soil around base of gas engine, exhaust, and near wellhead NOW appears mitigated. See photos #3, 4, 7, 8, 13,14.</p>				
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares berms w/ crude oil tanks.				
Corrective Action:					
Date:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLS	STEEL AST		40.829601,-104.327036
Comment:	Equalizer line connects both crude oil tanks.				
Corrective Action:					
Date:					

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares berms w/ produced H2O tank.			

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

--	--	--

**Inspected Facilities**Facility ID: 418212 Type: WELL API Number: 123-31853 Status: AB Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Shut-In | SI. Pumpjack & production equipment NOT in operation.  
Not sure why scout card shows Abandoned | AB.Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date:

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 07/30/2019 at approximately 13:48 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: SUNBURST INC  Location Name: Smuggler /16-10-62  Location ID: 418211  Well Name: Smuggler 16-10-62  API: 05-123-31853  Location County: Weld County, Colorado  Weather: Dry</p> <p>While there, I observed:  Wells: 1 well: Shut-In   SI.  Facility / Battery: ALL equipment appears shut-down.</p> <p>Follow-up to Field Inspection Report Doc #691200488 dated 09/24/2018.  3 of 4 Corrective Actions appears addressed.  1.) Oily Waste. Open 5-gallon bucket approximately half full of oily fluid.  Refer to Rule 907.e for guidance.  Properly treat or dispose of oily waste in accordance with Rule 907.e.  Corrective Action date: 10/25/2018.  * Open 5-gallon bucket approximately half full of oily fluid has been removed.  See photos #5, 6.  2.) Gas Engine &amp; wellsite. Stained soil around base of gas engine, exhaust, and near wellhead.  Mechanical Conditions (30 days).  Refer to Rule 605.d for guidance.  Corrective Action date: 10/25/2018.  * Stained soil around base of gas engine, exhaust, and near wellhead NOW appears mitigated.  See photos #3, 4, 7, 8, 13,14.  3.) Bradenhead does NOT appear plumbed to surface.  Mechanical Conditions.  Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.  Corrective Action date: 10/25/2018.  * Bradenhead NOW appears plumbed to surface.  See photos #3, 4.</p> <p>1 of 4 Corrective Actions appears NOT addressed.  1.) Weeds in and around tank berms treater, pumpjack and engine shed.  Refer to Rule 603.f.  Remove, manage, &amp; control weeds in tank berms. treater, pumpjack and engine shed.  Comply w/ Rule 603.f.  Corrective Action date: 10/05/2018.  * Weeds remain in and around tank berms, treater, pumpjack and engine shed.  See photos #3, 4.  Corrective Action date: 10/05/2018.  Original Corrective Action date remains applicable.  See photos #1, 2, 9-12.</p> <p>NO: NEW Corrective Actions observed on this inspection.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	07/31/2019



**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101195	Site photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4896710">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4896710</a>