

Inspection Photos

API: 05-073-06365

Operator: D90 ENERGY

Inspection Date: 7/25/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-073-06365 | Date: 7/25/2019

Inspection Photos



Photo 1. Facing north along the main road. The road was recently graded and widened. The side of the road was disturbed and needs to be revegetated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06365 | Date: 7/25/2019

Inspection Photos



Photo 2. A culvert along the main road is filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06365 | Date: 7/25/2019

Inspection Photos



Photo 3. Facing northeast toward the location. There is erosion occurring along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06365 | Date: 7/25/2019

Inspection Photos



Photo 4. Facing back toward the access road. Rocks are piled in the drainage which is causing stormwater to flow down the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06365 | Date: 7/25/2019

Inspection Photos



Photo 5. Old operator name remain on equipment and signs.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06365 | Date: 7/25/2019

Inspection Photos



Photo 6. Recently graded road has sandy soils.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06365 | Date: 7/25/2019