

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/31/2019

Submitted Date:

07/31/2019

Document Number:

694900124**FIELD INSPECTION FORM**Loc ID 335540 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 950 17TH STREET, SUITE 1900City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:20 Number of Comments2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289262	WELL	PR	03/01/2019	GW	045-13707	BURCKLE A1	PR
289263	WELL	PR	07/07/2011	GW	045-13706	Burckle Federal A2	PR
289264	WELL	PR	03/01/2019	GW	045-13705	BURCKLE A3	PR
289997	WELL	PR	03/01/2019	GW	045-13960	BURCKLE A7	PR
291710	WELL	PR	03/01/2019	GW	045-14516	BURCKLE A11	PR
291712	WELL	PR	03/01/2019	GW	045-14515	BURCKLE A9	PR
298250	WELL	PR	07/02/2011	GW	045-17096	BURCKLE FED CA A10	PR
298251	WELL	PR	08/15/2011	GW	045-17097	BURCKLE FED CA A12	PR
422091	WELL	PR	07/08/2011	GW	045-20490	Burckle Federal A14	PR
422095	WELL	PR	08/15/2011	GW	045-20491	Burckle Federal A13	PR

General Comment:[Follow up inspection from inspection # 689301168](#)

Location

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	5 tanks do not have Bbls on them.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	09/02/2019

Emergency Contact Number:	
Comment:	911
Corrective Action:	
Date:	

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Pregnent calf(knock out tank for ECD) not conected to anything.		
Corrective Action:	Comply with Rule 603.f .	Date:	09/02/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	livestock fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 8		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		,
Comment: in the same containment with 4 condensate tanks					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment: 1 heated					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: separate containment				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	STEEL AST		,
Comment: In the same containment with 2 produced water tanks.					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: Ramsey, Scott

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities						
Facility ID:	289262	Type:	WELL	API Number: 045-13707	Status: PR	Insp. Status: PR
Producing Well						
Comment:	plunger lift					
Corrective Action:						Date:
Facility ID:	289263	Type:	WELL	API Number: 045-13706	Status: PR	Insp. Status: PR
Producing Well						
Comment:	plunger lift					
Corrective Action:						Date:
Facility ID:	289264	Type:	WELL	API Number: 045-13705	Status: PR	Insp. Status: PR
Producing Well						
Comment:	plunger lift					
Corrective Action:						Date:
Facility ID:	289997	Type:	WELL	API Number: 045-13960	Status: PR	Insp. Status: PR
Producing Well						
Comment:	plunger lift					
Corrective Action:						Date:
Facility ID:	291710	Type:	WELL	API Number: 045-14516	Status: PR	Insp. Status: PR
Producing Well						
Comment:	plunger lift					
Corrective Action:						Date:
Facility ID:	291712	Type:	WELL	API Number: 045-14515	Status: PR	Insp. Status: PR
Producing Well						
Comment:	plunger lift					
Corrective Action:						Date:
Facility ID:	298250	Type:	WELL	API Number: 045-17096	Status: PR	Insp. Status: PR
Producing Well						
Comment:	plunger lift					
Corrective Action:						Date:
Facility ID:	298251	Type:	WELL	API Number: 045-17097	Status: PR	Insp. Status: PR
Producing Well						
Comment:	plunger lift					
Corrective Action:						Date:

Facility ID:	422091	Type:	WELL	API Number:	045-20490	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [plunger lift](#)

Corrective Action:

Date:

Facility ID:	422095	Type:	WELL	API Number:	045-20491	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [plunger lift](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Compaction				
		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 7/31/19 at approximately 10:00 AM, I, Inspector Scott Ramsey, conducted a Follow up inspection at Ursa Burckle A Pad at Location #335540 in Garfield County, Colorado.</p> <p>While there, I observed Normal production operations.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>5 tanks missing Bbls</p> <p>1 Knock out tank not hooked up</p> <p>Refer to photograph of observed compliance issue.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if corrective actions are identified).</p> <p>This is a summary of inspection report.</p>	ramseys	07/31/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900129	694900124	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4897363