



CC 0632-13-22  
Location # 335113



Danger sign by entrance is obstructed by weeds.



Danger sign by entrance is obstructed by weeds.

CC 0632-13-22  
Location # 335113



**Subsidence of unstable cut slope behind tank battery.**



**Subsidence of unstable cut slope behind tank battery.**

CC 0632-13-22  
Location # 335113



**Subsidence of unstable cut slope behind tank battery.**

**Subsidence of unstable cut slope behind tank battery.**

CC 0632-13-22  
Location # 335113



**Subsidence of unstable cut slope behind tank battery.**



**Subsidence of unstable cut slope behind tank battery.**

CC 0632-13-22  
Location # 335113



**CC 0632-13-22**  
**Location # 335113**



**8" black poly line exposed at entrance near tank battery and the cut off end comes out on other the side of roadway and entrance.**



**8" black poly line exposed at entrance near tank battery and the cut off end comes out on other the side of roadway and entrance.**

CC 0632-13-22  
Location # 335113



**8" black poly line exposed at entrance near tank battery and the cut off end comes out on other the side of roadway and entrance.**



**8" black poly line exposed at entrance near tank battery and the cut off end comes out on other the side of roadway and entrance.**

CC 0632-13-22  
Location # 335113



Approximately 35' piece of poly pipe along road N39.48783  
W108.24905



Approximately 35' piece of poly pipe along road N39.48783  
W108.24905

CC 0632-13-22  
Location # 335113



Approximately 35' piece of poly pipe along road N39.48783  
W108.24905



Approximately 35' piece of poly pipe along road N39.48783  
W108.24905